

Water Quality Inspector's Comments [REDACTED] Glenshane Road February 2023 Notes

01 February 2023: Visited [REDACTED] with [REDACTED] and [REDACTED]. Discussed the engineers report and the recommendations contained within. Continues to be no pollution issues.

16th February 2023: [REDACTED] have done some work on the access down to the lagoons where the drainage sump and bunded area was previously. The bunded area is no longer present. There is a concrete ring manhole in position where the sump was previously. There was a large bollard on top of the ring so I couldn't see in though I couldn't hear any water flowing. [REDACTED] wasn't on site and the person in the office wasn't aware of the new arrangements. I tried ringing [REDACTED] on the phone but his phone was off.

He has fixed the pipe down at the lagoons so there is no longer water leaking out of it onto the bank. He has installed a new length of pipe from the pump sump to the location of the leak. He has also installed a couple of posts which I assume is to provide extra protection against the connector fitting between the pipe sections from coming apart.

17th February 2023: Tried to ring [REDACTED] but no answer.

23rd February 2023: Spoke with [REDACTED] on the phone. He said they needed better access down to the lagoons area hence they removed the sump / bunded area. The drainage that would have gone to that area is now piped under the access track and into what [REDACTED] described as the middle lagoon. Due to the drainage arrangements outside [REDACTED] site on the A6, the amount of water coming to this point is also significantly reduced.

[REDACTED]