

4th April 2023: Met [REDACTED] on site and inspected with him, the new drainage arrangements for water from the car park area. The track on which the second part of the previous sump area was located has been stoned. This allows better access for maintenance of the existing lagoons. [REDACTED] was keen to emphasise that this will allow us to drive down any time we wish to inspect the lagoons and or the river. Manhole rings have been located where the first section of the sump area was previously. This allows inspection of the drainage concerned. Drainage is directed to the existing lagoons. Photos on content manager. Continues to be no pollution issues.

Also [REDACTED] has planted trees and wild flowers on the sloping bank along one edge of the track. He has also cut back (not removed) some of the trees on the walls of the existing lagoons. Removed some silt from Pond 2.

[REDACTED]
4th April 2023