

Internal Incident Report



Department of

Agriculture, Environment
and Rural Affairs

www.daera-ni.gov.uk

Incident Number

WR 2/14/0122

Incident Title

Landfill site [REDACTED]

Incident Date

20/05/2014 10:00:00

Investigation
Details

Former [REDACTED] sand and gravel site at [REDACTED] illegal dump under investigation by ECU. under repatriation scheme. br /
br /
may have been resold and current works onsite may be illegal. br /
br /
joint investigation WMU/ECUbr /
br /
no immediate obvious pollution signs at [REDACTED] /
br /
other recent incident WR 2/14/0025 RMcFaul sandwashings from adjacent [REDACTED] site still under investigation as pipework unestablished withing the waste site.

Officer Forename

[REDACTED]

Officer Surname

[REDACTED]

Pollution Confirmed

No

Source

[REDACTED]

Pollutant Category

[REDACTED]

Pollutant Sub Category

[REDACTED]

Cause

[REDACTED]

Pollution Severity

[REDACTED]

PCA

2

Alleged Polluter

[REDACTED]

Advisory Letter Issued

No

Fuel Laundering

No

Domestic Oil Spillage

No

Closed Period

No

Algal Bloom

No

X Compliance Breach

No

Fish Kill Severity

[REDACTED]

Fishkill Figures From

[REDACTED]

Kill Count

[REDACTED]

Easting

[REDACTED]

Northing

[REDACTED]

Report Executed by NIGOV [REDACTED] at 05/08/2026 10:15:28

Internal Incident Report



Incident Number

WR 2/19/0053

Incident Title

Waste re-pat site, [REDACTED]

Incident Date

10/04/2019 10:30:00

Investigation
Details

10/4/19

At approximately 1030, NIEA arrived at [REDACTED]. Present [REDACTED], [REDACTED] – Waste Repatriation team. Inspected ww on [REDACTED] which [REDACTED] stated was linked to the inspection chamber at the entrance to the [REDACTED]. Visually clean. Having spoken to a local farmer, we all proceeded to a field on the [REDACTED] from which we viewed a large proportion of both the [REDACTED] and the [REDACTED]. Panoramic photograph taken at 1123. Then all proceeded to the [REDACTED] site entrance which was locked. Entered the site and carried out a general inspection. Walked to wall of waste and climbed to top of same. All climbed except [REDACTED]. Observed WL in settlement pond behind wall of waste was c. 30cm from lowest point of bund. The settled solids was c. 30-40cm below WL. [REDACTED] and I returned to van to collect sampling equipment. Returned to waste wall and climbed to top. At 1345 collected investigation sample of water in settlement pond (WR2/19/0053A). Collected sample for TM and Tr Org analysis. Introduced tracing dye to settlement pond. Pic. Approached by two males from the direction of Lough Doo. [REDACTED] climbed down. [REDACTED] spoke with them while I remained in at the top of the wall of waste. On returning to the insp chamber, [REDACTED] had collected sample (at 1350) from insp chamber (WR2/19/0053B). All proceeded toward site entrance. At 1400, [REDACTED] collected sample from insp chamber (WR2/19/0053C). Proceeded to vans. Having wrote labels, labelled each of the six bottles. Placed in bags and cool box for transportation to lab. Departed the site. At 1640, deposited the sample bottles in the lab and signed sample reception logbook.

11/4/19

[REDACTED] checked dye test

12/4/19

[REDACTED] checked dye test

15/4/19

[REDACTED] checked dye test. No dye in inspection chamber. Raining heavily at time of inspection. Didn't climb up embankment due to risk of slipping.

16/4/19

[REDACTED] checked dye test

Officer Forename

[REDACTED]

Officer Surname

[REDACTED]

Pollution Confirmed

No

Source

Pollutant Category

Pollutant Sub Category

Cause

Pollution Severity

PCA

2

Alleged Polluter

Advisory Letter Issued

No

Fuel Laundering

No

Domestic Oil Spillage

No

Closed Period

No

Algal Bloom

No

X Compliance Breach

No

Fish Kill Severity

Fishkill Figures From

Kill Count	
Easting	
Northing	

Report Executed by NIGOV at 05/08/2026 10:16:49