

EXHIBIT [REDACTED] 1– Pollution Investigation WR4/23/0956
Location map A indicating relationship of photographs [REDACTED]





EXHIBIT [REDACTED] 2
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 1 – Crumlin River [REDACTED] – discoloured brown.

EXHIBIT [REDACTED] 3
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 2 – Dead fish [REDACTED]

EXHIBIT [REDACTED] 4
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 3 – Crumlin River [REDACTED] – visibly clear

EXHIBIT [REDACTED] 5
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 4 – Dead fish immediately upstream of visibly clear [REDACTED]

EXHIBIT [REDACTED] 6
Pollution Incident WR 4/23/0956




Photograph [REDACTED] 5 – Dead trout [REDACTED] immediately downstream of [REDACTED]

EXHIBIT [REDACTED] **7**
Pollution Incident WR 4/23/0956



Photograph [REDACTED] **6 – [REDACTED] discoloured brown immediately upstream of [REDACTED]**

EXHIBIT [REDACTED] 9 – Pollution Investigation WR 4/23/0956
Location Map B [REDACTED]



KEY




Flow direction

EXHIBIT [REDACTED] 10
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 8 – Visibly clear Stream [REDACTED] upstream [REDACTED]

EXHIBIT [REDACTED] 11
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 9 – Digger cleaning out sheugh immediately downstream [REDACTED]

EXHIBIT [REDACTED] 12
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 10 – tide mark on sheugh bank

EXHIBIT [REDACTED] 13
Pollution Incident WR 4/23/0956



Photograph [REDACTED] 11 – visibly clear stream immediately upstream [REDACTED]