Northern Ireland Environment Agency
www.daera-ni.gov.uk

Klondyke Building
Cromac Avenue
Gasworks Business Park
Malone Lower
BELFAST
BT7 2JA

[redacted]
Quinn Environmental Ltd
56 Craigmore Road
Garvagh
Coleraine
BT51 5HF

Our Ref: P0145/06A/V4

23rd October 2017

Dear Eamon,

**LISBANE LANDFILL SITE – CQA PLAN FOR LISBANE LANDFILL CAPPING**

I refer to the CQA Plan for Lisbane Landfill Capping, received by the Department on 19th October 2017. The Chief Inspector acknowledges the submission and confirms that it meets the requirements of the permit subject to the following condition:

- In accordance with the Landfill Regulations, soil cover >1m must be placed across the final restored landfill profile to enable after use to be achieved.

A CQA Validation Report will be required upon completion of each phase of cap and prior to the placement of restoration materials.

The Suspension Notice will be lifted following the submission and approval of the first CQA Validation Report.

An updated Site Specific Management Plan is also required prior to the deposit of restoration materials, please provide this plan as soon as possible.

If you have any queries in relation to the above please contact me on 028 9056 9505.

Yours sincerely,

[redacted]
Waste Management

Cc (email only)
[redacted], WDR & RT Taggart
[redacted], WDR & RT Taggart